Lick Creek - Winter 2007 Fieldwork Findings and Recommendations

Table A	-8: TARGETED O	UTREACH & EDUCAT				
Site ID	Name and Location	Targeted Education Type	Description	Agency for Follow-up	Priority for Further Action	Follow-up on- site inspection needed
CM-200	Wexford Woods Trail	Importance of streams	Stream bank armoring found behind Wexford Woods Trail	TBD	Low	No
SC-201	Kintail Dr.	Importance of streams	Homeowners refer to stream as drainage easement.	TBD	Low	No
TR-200	Uppercross Ct.	Importance of streams	Homeowners refer to stream as drainage easement.	TBD	Low	No
OT-100	Fox Ridge Apartments - Foxridge Crescent off Page Rd west of Page Rd Extension	Lawn care; trash	Noted very green grass and lots of trash coming out of untreated stormwater outfall	Durham County	Low	Yes
H-302	MeElhoney Homes Route 70 east of Mineral Springs	Materials storage	Manufactured home sales and repair. Uncovered and uncontained hazardous materials present, including a rusting Toluene barrel.	Durham County	High	Yes
H-300b	Undeveloped parcel South of McDonald's	Materials storage	This undeveloped parcel contains an unlabelled liquid stored outside behind a shed. Potential hazardous items litter the site.	Durham County	Medium	Yes
MI-350	Olive Branch Rd Homeowner	Materials storage	Fuel for irrigation pump stored on stream bank.	SWCD	Medium	Yes
RCH122, RCH151, RCH152	Neighborhood between Olive Branch Rd, Bookman, Rondelay	Septic and sump pump discharge; Buffer management	Established low density residential area on septic with 3 small first order streams running in back yards. Septic drain pipes and washer hookups discharging into stream. No chlorinators were noted on these three reaches, suds in stream and sewage smells were detected. Stream buffers are manicured and range from tree cover to turf grass. Check for chlorinators and interview homeowners.	DENR DWQ	High	Yes
MI-120	Control structure at large pond at Ravenstone	Stormwater pond maintenance	Education for HOA and property management company will likely be needed on the operation of the stream diversion structure.	City of Durham SWS BMP Inspection Program	Medium	Yes
TR-211	Wentz Rd.	Trash	Trash found behind houses on Wentz Rd. along stream corridor	Durham County	Medium	No
H-304	Jay Auto Sales - Route 70 at Hinesly	Vehicle Repair	Small auto repair and sales business. Did not access site.	Durham County	Low	Yes
H-305a	Kawasaki - Route 70	Vehicle Repair	Repair and sales of motorcycles & 4-wheelers. Vehciles are repaired inside.	Durham County	Low	No
H-303	Ward Trucking - Route 70	Vehicle Repair	Trucking operation. Did not access rear of site.	Durham County		Yes
MI-510	Power Easement north of Old Creedmor Rd	Vehicle Storage	Junkyard and/or car dumping site in power easement.	Durham County	Medium	Yes
H-300a	McDonald's Restaurant at Route 70 and Mineral Springs Rd	Wash water disposal	Wash area with hose and soap set up in dumpster pad area. Observed employee cleaning in this area which resulted in soapy water discharging to storm drain inlet near or in Route 70 ROW.	NCDOT and Durham County	High	Yes

Lick Creek - Winter 2007 Fieldwork Findings and Recommendations

Table A	-8: TARGETED O					
Site ID	Name and Location	Targeted Education Type	Description	Agency for Follow-up	Priority for Further Action	Follow-up on- site inspection needed
Н-306	Carolina Livery at Town and Country Homes on Route 70	Wash water disposal	Carolina Livery is operating bus and limo service out of manufactured home seller property. Observed Livery employees washing vehicles on asphalt driveway that drains to highway storm drain system.	Durham County	High	Yes
H-301	Miracle Touch LLC adjacent to McDonald's on Route 70	Wash water disposal	Small car wash/detailing business. Washing occurs on concrete pad that sheet flows to a grass channel.	Durham County	Medium	Yes
H-307	Burger King at Route 70 and Mineral Springs Rd	Wash water disposal	Evidence that wash water may be discarded in dumpster area which drains to curb cuts and stream. Grease storage should also be examined.	Durham County	Medium	Yes