



Appendix A: Subwatershed Results


This appendix presents the graphs and tables associated with each subwatershed.

Subwatershed 1

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	3.3%	12.4%	18.9%	-
Structural Stormwater Management Practices	0.8%	0.8%	0.6%	9.7%
Riparian Buffers	2.6%	0.5%	1.5%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	1.0%	0.4%	0.0%	0.1%
Total Reduction	7.8%	14.1%	21.0%	9.8%





Subwatershed 1




Subwatershed 2

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	0.8%	4.4%	10.7%	-
Structural Stormwater Management Practices	0.3%	0.2%	0.2%	1.5%
Riparian Buffers	2.7%	0.8%	3.0%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	1.4%	0.7%	0.1%	0.0%
Total Reduction	5.3%	6.1%	14.0%	1.6%





Subwatershed 2





Subwatershed 3

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	2.2%	11.2%	17.2%	-
Structural Stormwater Management Practices	0.1%	0.2%	0.1%	1.5%
Riparian Buffers	2.5%	0.7%	1.9%	-
Septic System Education	0.2%	0.1%	0.0%	0.0%
Septic System Inspection/Repair	2.8%	1.4%	0.1%	0.2%
Total Reduction	7.8%	13.7%	19.3%	1.7%





Subwatershed 3





Subwatershed 4

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	2.9%	11.0%	17.1%	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	1.9%	0.4%	1.1%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	0.8%	0.3%	0.0%	0.1%
Total Reduction	5.6%	11.7%	18.2%	0.1%





Subwatershed 4





Subwatershed 5

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	0.0%	0.0%	0.0%	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	2.7%	0.8%	2.7%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	1.1%	0.6%	0.0%	0.1%
Total Reduction	3.9%	1.4%	2.7%	0.1%





Subwatershed 5




Subwatershed 6

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	0.4%	1.7%	3.5%	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	3.9%	1.0%	4.0%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	1.2%	0.6%	0.0%	0.1%
Total Reduction	5.6%	3.4%	7.5%	0.1%





Subwatershed 6





Subwatershed 7

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	0.9%	4.3%	10.6%	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	2.5%	0.6%	3.1%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	0.8%	0.4%	0.0%	0.1%
Total Reduction	4.3%	5.4%	13.7%	0.1%





Subwatershed 7





Subwatershed 8

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	0.3%	1.8%	4.0%	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	2.5%	0.9%	2.9%	-
Septic System Education	0.2%	0.1%	0.0%	0.0%
Septic System Inspection/Repair	2.4%	1.4%	0.1%	0.2%
Total Reduction	5.3%	4.2%	6.9%	0.2%





Subwatershed 8





Subwatershed 9

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	0.0%	0.2%	0.3%	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	3.6%	1.0%	3.9%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	0.8%	0.4%	0.0%	0.1%
Total Reduction	4.5%	1.6%	4.2%	0.1%





Subwatershed 9





Subwatershed 10

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	0.9%	5.6%	10.8%	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	3.3%	1.1%	3.7%	-
Septic System Education	0.2%	0.1%	0.0%	0.0%
Septic System Inspection/Repair	2.8%	1.6%	0.1%	0.2%
Total Reduction	7.2%	8.4%	14.6%	0.2%





Subwatershed 10



Subwatershed 11

Additional Percent Reduction - Beyond Practices Currently in Place				
	TN	TP	TSS	Bacteria
Erosion and Sediment Control	-	-	-	-
Structural Stormwater Management Practices	-	-	-	-
Riparian Buffers	4.2%	1.6%	3.5%	-
Septic System Education	0.1%	0.0%	0.0%	0.0%
Septic System Inspection/Repair	0.9%	0.6%	0.0%	0.0%
Total Reduction	5.2%	2.3%	3.5%	0.0%



Subwatershed 11

